

**Inspection Photo**  
**Kelley 34-14**  
**API # 045-10055**  
**Inspection # 689302279**



**Location Photo #1**



**Location Photo #2**

**Inspection Photo  
Kelley 34-14  
API # 045-10055  
Inspection # 689302279**



**Location Photo #3**



**Location Photo #4, unused equipment near wellheads**

**Inspection Photo  
Kelley 34-14  
API # 045-10055  
Inspection # 689302279**



**Location Photo #5, mechanical condition on 3" valve, oily stained ground**

**Location Photo #6, oily stained ground**

**Inspection Photo  
Kelley 34-14  
API # 045-10055  
Inspection # 689302279**



**Location Photo #7, holes in secondary containment liner**



**Location Photo #8, holes in secondary containment liner**

**Inspection Photo  
Kelley 34-14  
API # 045-10055  
Inspection # 689302279**



**Location Photo #9, holes in secondary  
containment liner**

**Location Photo #10, holes in secondary  
containment liner**

**Inspection Photo  
Kelley 34-14  
API # 045-10055  
Inspection # 689302279**



**Location Photo #11, holes in secondary containment liner**



**Location Photo #12, holes in secondary containment liner**

**Inspection Photo  
Kelley 34-14  
API # 045-10055  
Inspection # 689302279**



**Location Photo #13, holes in secondary  
containment liner**