

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/31/2018

Submitted Date:

10/31/2018

Document Number:

691200703**FIELD INSPECTION FORM**
 Loc ID 330219 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|----------------|-------|--|---------------------------------|
| Arthur, Denise | | denise.arthur@state.co.us | |
| , | | NBL_DJBU_Inspections@NB LENERGY.COM | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 250842 | WELL | PR | 04/01/2018 | OW | 123-18645 | JOHNSON A 32-06 | PR |

General Comment:

This is a WELL inspection.
Refer to FIR #691200701 and/or Location ID #330218 for Battery facility, Equipment info.

Location

| | | | |
|--------------------|----------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Adequate | | |
| Corrective Action | | Date: | |

Overall Good: ☐

| | | | |
|----------------------|----------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action: Date:

| | | | |
|---------------------------|---|-------|------------|
| Good Housekeeping: | | | |
| Type | WEEDS | | |
| Comment: | Weed encroachment around wellsite. Statewide weeds requirements. (10 days). Refer to Rule 603.f for guidance. | | |
| Corrective Action: | Remove, manage, & control weeds around wellsite. Comply with Rule 603.f . | Date: | 11/12/2018 |

Overall Good: ☐

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|--------------------|------------|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Iron panel | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|---|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: | # | | |
| Comment: | Refer to FIR #691200701 and/or Location ID #330218 for additional Equipment info. | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|----------|---|----------|---------------------|---------|-----------------------|
| | | | CENTRALIZED BATTERY | | 40.449382,-104.581106 |

| | | | | | | |
|--------------------|---|---------------------|---------------------|-------------|-------|--|
| Comment: | This Centralized Battery serves 3 Location IDs (330218, 330219, 420827). Refer to FIR #691200701 and/or Location ID #330218 for Tanks & Berms info. | | | | | |
| Corrective Action: | | | | | Date: | |
| Paint | | | | | | |
| Condition | | | | | | |
| Other (Content) | | | | | | |
| Other (Capacity) | | | | | | |
| Other (Type) | | | | | | |
| Berms | | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | | |
| | | | | | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | Date: | |
| Venting: | | | | | | |
| Yes/No | NO | | | | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | Date: | |
| Flaring: | | | | | | |
| Type | | | | | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | Date: | |

| Inspected Facilities | | | | | | | | | |
|----------------------|--------|--|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 250842 | Type: | WELL | API Number: | 123-18645 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | | PR. | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |
| BradenHead | | | | | | | | | |
| Comment: | | Bradenhead appears plumbed to surface. | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 401818975 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4627691 |
| 691200704 | Site photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4627689 |