

**Inspection Photo
Brynildson 19-8
API # 045-13518
Inspection # 689302285**



Location Photo #1



Location Photo #2

**Inspection Photo
Brynildson 19-8
API # 045-13518
Inspection # 689302285**



Location Photo #3, Oil stained rock in battery containment.