

**Inspection Photo**  
**Brynildson 14A-20-692**  
**API # 045-17146**  
**Inspection # 689302290**



**Location Photo #1**



**Location Photo #2**

**Inspection Photo  
Brynildson 14A-20-692  
API # 045-17146  
Inspection # 689302290**



**Location Photo #3**



**Location Photo #4, Stained rock below valves.**



**Inspection Photo  
Brynildson 14A-20-692  
API # 045-17146  
Inspection # 689302290**



**Location Photo #5, Stained rock in battery containment.**



**Location Photo #6, Missing BBL capacity, Inaccurate sign, Non legible.**

**Inspection Photo  
Brynildson 14A-20-692  
API # 045-17146  
Inspection # 689302290**



**Location Photo #7, Non legible BBL capacity.**



**Location Photo #8, Non legible BBL capacity.**