

**Inspection Photo
Shideler 29-11C
API # 045-11853
Inspection # 689302297**



Location Photo #1



**Location Photo #2 Unused equipment in
battery containment.**

**Inspection Photo
Shideler 29-11C
API # 045-11853
Inspection # 689302297**



Location Photo #3, Oil stained rock in battery containment.



Location Photo #4, Oil stained rock in battery containment.

**Inspection Photo
Shideler 29-11C
API # 045-11853
Inspection # 689302297**



Location Photo #5, Oil stained rock in battery containment. Mechanical condition of valves.



Location Photo #6, Stained rock under and around separator.

**Inspection Photo
Shideler 29-11C
API # 045-11853
Inspection # 689302297**



Location Photo #7, Oily stained rock under separator by burner unit.



Location Photo #8, Mechanical condition of lubricator on wellhead.

**Inspection Photo
Shideler 29-11C
API # 045-11853
Inspection # 689302297**



Location Photo #9, Mechanical condition of valves in flow line.



Location Photo #10, Mechanical condition of lubricator on wellhead