

Inspection Photos

Operator: BP Production

API: 05-067-08631

Date: 10/24/2018




Photo 1. View of the project area from the eastern well pad entrance facing center. Stormwater flows from the well pad are eroding a channel approximately 6 inches wide and deep that flows eastward, down the access road. This needs stabilization.



Photo 2. View of the northeastern project area from the eastern corner facing northward. Revegetation is progressing with grasses such as crested wheatgrass (*Agropyron cristatum*), and intermediate wheatgrass (*Thinopyron intermedium*).





Photo 3. View of the southern project area from the edge of the working area facing southward. Soil is stockpiled here.



Photo 4. View of the western project area from the southern corner facing northward.



Photo 5. View of Russian thistle (*Salsola tragus*) debris within the project area that is broken off and will blow.