

Inspection Photos

Operator: BP Production

API: 05-067-05787

Date: 10/24/2018



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Revegetation is progressing with grasses and shrubs such as sand dropseed (*Sporobolus cryptandrus*) and rubber rabbitbrush (*Chrysothamnus nauseosus*).



Photo 3. View of the northern project area from the northeastern corner facing westward.



Photo 4. View of erosional channel in the southeastern project area.



Photo 5. View of erosional rilling within the eastern project area.



Photo 6. View of erosional channel within the northern file slope, approximately 2.5 feet wide and deep>