

**Inspection Photo**  
**Roles 13-10**  
**API # 045-06953**  
**Inspection # 689302325**



**Location Photo #1**



**Location Photo #2 secondary containment repaired.**

**Inspection Photo  
Roles 13-10  
API # 045-06953  
Inspection # 689302325**



**Location Photo #3, secondary containment repaired.**



**Location Photo #4, Access road storm water issue unresolved.**

**Inspection Photo  
Roles 13-10  
API # 045-06953  
Inspection # 689302325**



**Location Photo #5, Sediment being moved onto location. Rilling occurring in middle of road.**



**Location Photo #6, Sediment being moved onto location.**

**Inspection Photo  
Roles 13-10  
API # 045-06953  
Inspection # 689302325**



**Location Photo #7, Sediment being moved onto location.**



**Location Photo #8, Sediment being moved off location.**



**Inspection Photo**  
**Roles 13-10**  
**API # 045-06953**  
**Inspection # 689302325**



**Location Photo #9, Sediment being moved off location.**