

Inspection Photos 9-20-18
JA Farms 1, Location ID 313873
API: 05-087-07380
Operator Smith Oil Properties, Inc - #79905



Photo #1
Former Spill area (Doc #2230022) Looking Northeast



Photo #2
Localized oil stained soil at pumping unit.



Inspection Photos 9-20-18
JA Farms 1, Location ID 313873
API: 05-087-07380
Operator Smith Oil Properties, Inc - #79905



Photo #3
Accumulations of lube oil at base of pumping unit



Photo #4
Looking north, areas of surface impact along former south and west berms of pit facility #109709.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos 9-20-18
JA Farms 1, Location ID 313873
API: 05-087-07380
Operator Smith Oil Properties, Inc - #79905



Photo #5
Pit Facility ID #109708 Looking southwest



Photo #6
Former skim pit (Fac ID #109707) excavation looking west. Oily waste along top of west wall.



Inspection Photos 9-20-18
JA Farms 1, Location ID 313873
API: 05-087-07380
Operator Smith Oil Properties, Inc - #79905



Photo #7
Localized oily waste and buried plastic liner east of pit complex looking west.



Photo #8
Stockpile of dirt mixed with gravel on former battery location. Some small localized areas of oil staining in disturbed areas.

