

Inspection Photos  
Location Name: Mutual 01-17H  
Location ID: 324757



**Photo 1. Overview of location taken at entrance facing northeast.**

Inspection Photos  
Location Name: Mutual 01-17H  
Location ID: 324757



**Photo 2. Stained soil inside former equipment berm.  
Stored piping in background of photo.**



**Photo 3. Debris on location.**

Inspection Photos  
Location Name: Mutual 01-17H  
Location ID: 324757



**Photo 4. Stained soil inside equipment berm.**



**Photo 5. Equipment stored on location.**

Inspection Photos  
Location Name: Mutual 01-17H  
Location ID: 324757



Photo 6. Tanks with open hatches and no labels.



Photo 7. No berm.

Inspection Photos  
Location Name: Mutual 01-17H  
Location ID: 324757



Photo 8. Example of trash and debris on location.



Photo 9. Example of trash and debris on location in left background of photo.

Inspection Photos  
Location Name: Mutual 01-17H  
Location ID: 324757



Photo 10. Stained soil and open rat hole at wellhead.



Photo 11. Stained soil and trash/debris.