

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/02/2018

Submitted Date:

11/05/2018

Document Number:

693700063

FIELD INSPECTION FORM

Loc ID 415940 Inspector Name: ALLISON, RICK On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
MacLaren, Joe		joe.maclaren@state.co.us	
Inspections, Noble		NBL_DJBU_Inspections@NB LENERGY.COM	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
416035	WELL	PR	06/30/2010	OW	123-31237	DILLARD USX AB 09-99HZ	EI
458651	SPILL OR RELEASE	AC			-	Dillard USX AB 09-99HZ	EI

General Comment:

Inspected Facilities

Facility ID: 416035 Type: WELL API Number: 123-31237 Status: PR Insp. Status: EI

Facility ID: 458651 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental

Waste Management:

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil	Other	Adequate		
Comment	Impacted soil is maintained in excavation and directly loaded into dump trucks for disposal. Clean backfill staged onsite.			
Corrective Action				Date:

Spill/Remediation:

Comment: COGCC inspection of reported produced water dumpline release. Release at 90-degree fitting on steel dumpline. See photo attached that shows corroded threads and hole in fitting. Release occurred near produced water vessel. Excavation underway and extent not defined at time of site visit. Operator to continue reporting on Form 19 Supplemental Report including root cause and corrective action for produced water corrosion of threaded 90 degree joint. Production at this location began June 2010.

Corrective Action: Date:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693700065	Produced water dumpline fitting	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4640065
693700066	Excavation at dumpline release	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4640066