

# Inspection Photos

11/8/2018

Operator: WESTERN OPERATING COMPANY -  
95620

Location ID: 312291

Inspection Doc. Number: 682504107

Logan County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC



**Photo 1:** Photo taken from the east end of the pad, facing east. Photo shows additional reclamation activities appear to have been conducted on the spill areas to the south of the pit. Photo also shows that no sediment, erosion or stabilization controls have been installed.





**Photo 2:** Photo taken from the east end of the pad, facing east. Though additional reclamation activities appear to have been conducted, no sediment, erosion or stabilization controls have been installed, allowing for stormwater erosion degradation to recur.





**Photo 3:** Photo taken from the east end of the pit, facing south. Photo shows additional reclamation activities appear to have been conducted on the spill areas to the south of the pit. Photo also shows that no sediment, erosion or stabilization controls have been installed.





**Photo 4:** Photo taken from the east end of the pit, facing east. Though additional reclamation activities appear to have been conducted, no sediment, erosion or stabilization controls have been installed, allowing for stormwater erosion degradation to recur.





**Photo 5:** Photo taken from the southeast end of the pit, facing east. Photo shows additional reclamation activities appear to have been conducted on the spill areas to the south of the pit. However, areas appear to have been seeded up/down the slope rather than parallel to the contour. This may likely contribute to future erosion concerns as the furrows have created a straight path that will allow stormwater to concentrate and accelerate downslope. Photo also shows that no sediment, erosion or stabilization controls have been installed.





**Photo 6:** Photo taken from the southeast end of the pit, facing north. Photo shows additional reclamation activities appear to have been conducted on the spill areas to the south of the pit. Photo also shows that no sediment, erosion or stabilization controls have been installed.





**Photo 7:** Photo taken from the southeast end of the pit, facing west. See comments under photo 5.





**Photo 8:** Photo taken from the southwest end of the pit, facing west. See comments under photo 5.





**Photo 9:** Photo taken from the southwest end of the pit, facing north. Photo shows additional reclamation activities appear to have been conducted on the spill areas to the south of the pit. Photo also shows that no sediment, erosion or stabilization controls have been installed.





**Photo 10:** Photo taken from the west end of the location, facing west. Photo shows gully erosion due to stormwater runoff from the pad. Photo shows erosion has not been repaired and no BMPs have been installed to mitigate degradation.





**Photo 11:** Photo taken from the west end of the location, facing east. Photo shows gully erosion due to stormwater runoff from the pad. Photo shows erosion has not been repaired and no BMPs have been installed to mitigate degradation.





**Photo 12:** Photo taken from the west end of the location, facing east. Photo shows gully erosion due to stormwater runoff from the pad. Photo shows erosion has not been repaired and no BMPs have been installed to mitigate degradation.