

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/02/2018

Submitted Date:

11/05/2018

Document Number:

693700067**FIELD INSPECTION FORM**
 Loc ID 415892 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 10629Name of Operator: FIFTH CREEK ENERGY OPERATING COMPANY LLCAddress: 5251 DTC PKWY STE 420City: GREENWOOD State: CO Zip: 80111**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**1 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Barber, Matt		mbarber@hpres.com	
Singer, Sheila		ssinger@hpres.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
453495	SPILL OR RELEASE	AC	12/21/2017		-	Critter Creek 5-10H	EI
457128	SPILL OR RELEASE	CL	10/19/2018		-	Well stuffing box failure CritrCrk 5-10H	EI

**General Comment:**

Inspected Facilities							
Facility ID:	453495	Type:	SPILL OR	API Number:	-	Status: AC	Insp. Status: EI
Facility ID:	457128	Type:	SPILL OR	API Number:	-	Status: CL	Insp. Status: EI

**Environmental****Spill/Remediation:**

Comment: COGCC followup to spill closure for spill 457128 and inspection of unresolved spill 453495 Fifth Creek spill on 12/19/2017: 1 bbl of produced water and 2 bbls of Crude Oil was released outside of containment from the heater treater on the well pad of the Critter Creek 5-10H. The cause of the spill was determined to be due to the gasket on the flange half way up the heater treated failed. Once the leak was discovered a crew was dispatched to location and 1 bbl of produced water and 2 bbls of Crude Oil were recovered.

Corrective Action: Operator submit Form 19 Supplemental Report for spill ID 453495 and include root cause/corrective action for release and documentation of remediation efforts (soil removed/disposed and confirm soil sample results).

Date: 12/05/2018

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401833093	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4640073">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4640073</a>
693700068	Heater Treater Gasket	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4640067">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4640067</a>
693700069	Overview spill 457128	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4640068">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4640068</a>
693700070	Overview spill 453495	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4640069">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4640069</a>