

# Construction and Stormwater Inspection

November 14, 2018

Operator: PDC ENERGY INC - #69175

Location ID: 453057

Inspection Document #: 682404206

Weld County, CO

SENW Section 8 T4N R64W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Challenger /4N64W08  
1-9  
Location ID: 453057



**Photo 1.** Photo taken from the southeastern perimeter of the pad, facing Northeast. Photo illustrates a ditch and berm BMP that has been installed around the entire perimeter of the location. Berm has been left unconsolidated. An unconsolidated berm BMP is not a proper functioning BMP, as the unconsolidated material becomes a source of potential pollution itself. Operator shall ensure this BMP is properly stabilized as it could be susceptible to wind and water erosion.



**Photo 2.** Photo taken from the northeastern perimeter of the locatoin, facing West. Photo illustrates the topsoil stockpile which has been temporarily stabilized with equipment tracking.



Inspection Photos  
Location Name: Challenger /4N64W08  
1-9  
Location ID: 453057



**Photo 3.** Photo taken from the northeastern perimeter of the location, facing West. See comments under Photo 1 5 2.



**Photo 4.** Photo taken from the northwestern perimeter of the location, facing South. See comments under Photo 1.



Inspection Photos  
Location Name: Challenger /4N64W08  
1-9  
Location ID: 453057



**Photo 5.** Photo taken from the western perimeter of the location, facing East. Operator in-process of stabilizing the pad with road base.



**Photo 6.** Photo taken from the southwestern perimeter of the pad, facing South. See comments under Photo 2.

Inspection Photos  
Location Name: Challenger /4N64W08  
1-9  
Location ID: 453057



**Photo 7.** Photo taken from the southwestern perimeter of the production facility, facing South. See comments under Photo 1.



**Photo 8.** Photo taken from the southeastern perimeter of the production facility, facing North. See comments under Photo 1.