

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/17/2018

Submitted Date:

11/17/2018

Document Number:

689302369**FIELD INSPECTION FORM**

Loc ID 334906 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Elsener,		COGCC.inspections@caerus oilandgas.com	<a href="#">all Piceance inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271324	WELL	TA	05/01/2018	GW	045-09865	BENZEL 2-16B (I2W)	TA

**General Comment:**10 day MIT notification recieved. Document #401820772. D&B water services on site to perform test.

**Inspected Facilities**Facility ID: 271324 Type: WELL API Number: 045-09865 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily AbandonedReminder: EQUIPMENT PRESENT/DISCONNECTEDComment:

Starting psi -411  
5 min- psi- 410  
10 min- psi- 410  
15 min- psi-410  
1-PSI loss

Starting BH psi- 0  
Ending BH psi - 0

Corrective Action: Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689302371	Inspection photo 689302371	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4649016">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4649016</a>