

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/19/2018

Submitted Date:

11/19/2018

Document Number:

689302384**FIELD INSPECTION FORM**
 Loc ID 335127 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10531Name of Operator: VANGUARD OPERATING LLCAddress: 5847 SAN FELIPE #3000City: HOUSTON State: TX Zip: 77057**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**14 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Aaron, Axelson	230-0926	aaxelson@vnrenergy.com	<a href="#">Sr. Production Foreman</a>
Ghan, Scott	970-744-8128	sghan@vnrenergy.com	<a href="#">SR. EH&amp;S</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287515	WELL	PR	12/10/2008	GW	045-12998	PLATZER 33D-27-692	PR
287516	WELL	PR	12/10/2008	GW	045-12997	PLATZER 33B-27-692	PR
287517	WELL	PR	03/07/2007	GW	045-12996	PLATZER FEDERAL 43B-27-692	PR
287518	WELL	PR	03/16/2007	GW	045-12995	PLATZER FEDERAL 43D-27-692	PR

**General Comment:**[Routine Field Inspection.](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action:		Date:	

Overall Good: ☒

Emergency Contact Number:

Comment: 1-800-921-8252

Corrective Action:

Date:

**Good Housekeeping:**

Type	WEEDS		
Comment:			
Corrective Action:		Date:	
Type	DEBRIS		
Comment:			
Corrective Action:		Date:	
Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Panel gates		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panel fence		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panel fence		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	Chemical unit at wellhead		
Corrective Action:		Date:	

Type: Plunger Lift	# 4		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 6		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	4	300 BBLs	STEEL AST		,	
Comment:	Centralized battery. 1 heated tank					
Corrective Action:					Date:	

**Paint**

Condition	Adequate	
Other (Content)	Methanol tank	
Other (Capacity)	500 gallon	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	YES	
Comment:	Bradenhead valves open to vent.	
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	287515	Type:	WELL	API Number:	045-12998	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	287516	Type:	WELL	API Number:	045-12997	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	287517	Type:	WELL	API Number:	045-12996	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	287518	Type:	WELL	API Number:	045-12995	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap						
		Gravel				
		Compaction				
Culverts						
Berms						

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689302385	Inspection photo 689302385	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4649759">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4649759</a>