

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/30/2018

Submitted Date:

11/13/2018

Document Number:

692400342**FIELD INSPECTION FORM**Loc ID 436801 Inspector Name: Colby, Lou On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10598Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLCAddress: 123 ROBERT S KERR AVECity: OKLAHOMA CITY State: OK Zip: 73102**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Neidel, Kris		kris.neidel@state.co.us	
		sandridgeenvironmental@sandridgeenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
436790	WELL	PR	07/13/2015	OW	057-06526	Surprise Unit 2-08H	RI

General Comment:

This is an Interim Reclamation & Stormwater focused Inspection. Inspection conducted on 10/30/18; Data review & consultation with EPS staff completed on 11/13/18.

Inspected Facilities									
Facility ID:	436790	Type:	WELL	API Number:	057-06526	Status:	PR	Insp. Status:	RI

--

Environmental**Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Drill Cuttings	Piles			
Comment	Cuttings pile remains on Southeast Corner of site, adjacent to entry. Consultation with NW EPS, indicated Operator reported that cuttings were scheduled for removal. Direct any questions to NW EPS, Kris Neidel.			
Corrective Action	Remove all stored E&P waste by 12/13/18. Respond with FIRR when CA is complete, or if CA was completed before receipt of this Inspection.			Date: 12/13/2018

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: This Location is within a Sensitive Wildlife Habitat; Greater Sage Grouse, and approximately 1.25 miles from an active lek site (Ptar Lek).**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING _____

Comment Corrective Action Date _____1002b. SOIL REMOVAL AND
SEGREGATION _____Comment Corrective Action Date _____

1002c. PROTECTION OF SOILS _____

Comment Corrective Action Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment Corrective Action Date _____1003a. Waste and Debris removed? PassComment Corrective Action Date _____Unused or unneeded equipment onsite? PassComment Corrective Action Date _____Pit, cellars, rat holes and other bores closed? PassComment Corrective Action Date _____

Guy line anchors marked? _____

Comment Corrective Action Date _____

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: Corrective Action:

Date _____

Overall Final Reclamation

Well Release on Active Location ☐Multi-Well Location ☐**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Erosion is occurring on cut & fill slopes; sediment is migrating onto & off of Location; site degradation is occurring. Wattles have failed in areas. Proper Interim reclamation including revegetation will help stabilize these areas. Stormwater erosion will need to be controlled throughout the reclamation process.

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Temporary remedies can be employed to address sediment migration & stabilization of slopes until incorporation of Storm water plan with interim reclamation activities required in Reclamation Section (CA Date 6/3/19).

Date: 12/14/2018

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401838197	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4643905
692400355	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4643904