

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/15/2018

Submitted Date:

11/15/2018

Document Number:

689702074**FIELD INSPECTION FORM**Loc ID 324001 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**17 Number of Comments9 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
, Caerus Piceance		COGCC.inspections@caerus oilandgas.com	Piceance inspections only
Kellerby, Shaun		shaun.kellerby@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211460	WELL	SI	01/01/2018	GW	045-07220	TEXACO FEE 6217	SI

**General Comment:**

Routine FIU General Field Inspection

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L		Date:
Type	Main		
comment:			
Corrective Action	L		Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	The phone number for local emergency services (911 where available) is not posted on battery sign.		
Corrective Action:	Install sign to comply with Rule 210.b.		Date: 01/16/2019
Type	CONTAINERS		
Comment:	3 unlabeled containers.		
Corrective Action:	Install sign to comply with Rule 210.d.		Date: 01/16/2019
Type	TANK LABELS/PLACARDS		
Comment:	500 gallon 5 w oil tank not correctly labeled.		
Corrective Action:	Install sign to comply with Rule 210.d.		Date: 01/16/2019
Emergency Contact Number:			
Comment:	1-800-791-7691		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	Sheet metal debris and dead weeds outside of tank battery fence.		
Corrective Action:	Comply with Rule 603.f .		Date: 12/16/2018
Type	UNUSED EQUIPMENT		
Comment:	Unused compressor unit stored at tank facility.		
Corrective Action:	Comply with Rule 603.f .		Date: 02/16/2019
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
		<= 1 bbl	
Comment:	Oily stained gorund surface around compressor inside of battery facility fenced area.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.		Date: 12/16/2018
	Separator	<= 1 bbl	
Comment:	Unmarked 5 gallon buckett at separator with stained ground surface.		

Corrective Action: Properly treat or dispose of oily waste in accordance with 907.e.		Date: 12/16/2018	
In Containment: No			
Comment: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>			
<input type="checkbox"/> Multiple Spills and Releases?			

  

<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	

  

<b>Equipment:</b>			corrective date
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	55 gallon drum marked condensate in corner with compressor has no secondary containment. 3 unmarked containers setting inside of tank facility fenced area.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:	1 at well 1 at tank battery facility		
Corrective Action:		Date:	

  

<b>Tanks and Berms:</b>					
Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

  

<b>Paint</b>	
Condition	Adequate
Other (Content)	
Other (Capacity)	500 gallons
Other (Type)	

  

<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Other	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:	Poly type			
Corrective Action:				Date:

  

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	<50 BBLS	STEEL AST		,
Comment:					

Corrective Action:		Date:	
--------------------	--	-------	--

**Paint**

Condition		
Other (Content)	30 w oil	
Other (Capacity)	500 gallons	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: inside of tank battery berm.				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					
Date:					

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Insufficient	Base Sufficient	Inadequate
Comment: Spills not cleaned up in berm. Hole in berm liner.				
Corrective Action: Maintain berm wall/liner. Maintain housekeeping in berm.				Date: 12/16/2018

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	211460	Type:	WELL	API Number:	045-07220	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned      Reminder: _____									
Comment: _____									
Corrective Action: _____      Date: _____									

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Fail	3 containers with no secondary containment.
Compaction	Pass					
		Gravel	Pass			
Gravel	Pass					

Comment: [Containers at tank facility have no secondary containment.](#)Corrective Action: [Install or repair required BMPs per Rule 1002.f.](#)

Date: 12/16/2018

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401842747	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4647776">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4647776</a>
689702075	Inspection 689702074 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4647747">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4647747</a>