

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/26/2018

Submitted Date:

11/26/2018

Document Number:

691200844

FIELD INSPECTION FORM

Loc ID 419171 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1775 SHERMAN STREET - STE 3000
City: DENVER State: CO Zip: 80203

Findings:

18 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
419165	WELL	SI	10/01/2017	OW	123-32162	Kaiser 6-10	PR
419170	WELL	SI	04/01/2017	OW	123-32164	Kaiser 7-10	PR
430933	WELL	SI	06/01/2018	OW	123-36333	Kaiser 25-10	PR
430935	WELL	PR	08/01/2018	OW	123-36335	Kaiser 921-10	PR

General Comment:

This is a MULTIPLE WELL inspection (4-wells).
Refer to FIR #691200842 and/or Battery Facility ID #445804 for Battery & additional Equipment information.
Follow-up to FIR #673802643 dated 11/12/2015.
2 of 2 Corrective Action items have been addressed.

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	4 - Wells have adequate signs.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds have been cleared from location. This addresses the CA item from FIR #673802643 dated 11/12/2015.		
Corrective Action:			Date:
Type	OTHER		
Comment:	Stained soil around Kaiser 25-10 (API: 05-123-36333) wellsite appears to be remediated. This addresses the CA item from FIR #673802643 dated 11/12/2015.		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No _____			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	OTHER		
Comment:	Refer to FIR #691200842 and/or Battery Facility ID #445804 for additional Fencing information.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	4 - Wells have iron panel fencing.		
Corrective Action:			Date:
Equipment:			
			corrective date
Type: Other	#		
Comment:	Refer to FIR #691200842 and/or Battery Facility ID #445804 for additional Equipment information.		
Corrective Action:			Date:

Type: Plunger Lift	# 4	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.507843,-104.651596
Comment:	This Centralized Battery serves 2 Location IDs (310453, 419171). Refer to FIR #691200842 and/or Battery Facility ID #445804 for Tanks & Berms information.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities			
Facility ID: <u>419165</u>	Type: <u>WELL</u>	API Number: <u>123-32162</u>	Status: <u>SI</u> Insp. Status: <u>PR</u>
Producing Well			
Comment: <u>PR. Valves open at well.</u>	Corrective Action: <input style="width: 100%;" type="text"/>		Date: <input style="width: 50%;" type="text"/>
BradenHead			
Comment: <u>Bradenhead appears plumbed to surface.</u>	Corrective Action: <input style="width: 100%;" type="text"/>		Date: <input style="width: 50%;" type="text"/>
Facility ID: <u>419170</u>	Type: <u>WELL</u>	API Number: <u>123-32164</u>	Status: <u>SI</u> Insp. Status: <u>PR</u>
Producing Well			
Comment: <u>PR. Valves open at well.</u>	Corrective Action: <input style="width: 100%;" type="text"/>		Date: <input style="width: 50%;" type="text"/>
BradenHead			
Comment: <u>Bradenhead appears plumbed to surface.</u>	Corrective Action: <input style="width: 100%;" type="text"/>		Date: <input style="width: 50%;" type="text"/>
Facility ID: <u>430933</u>	Type: <u>WELL</u>	API Number: <u>123-36333</u>	Status: <u>SI</u> Insp. Status: <u>PR</u>
Producing Well			
Comment: <u>PR. Valves open at well.</u>	Corrective Action: <input style="width: 100%;" type="text"/>		Date: <input style="width: 50%;" type="text"/>
BradenHead			
Comment: <u>Bradenhead appears plumbed to surface.</u>	Corrective Action: <input style="width: 100%;" type="text"/>		Date: <input style="width: 50%;" type="text"/>
Facility ID: <u>430935</u>	Type: <u>WELL</u>	API Number: <u>123-36335</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment: <u>PR. Valves open at well.</u>	Corrective Action: <input style="width: 100%;" type="text"/>		Date: <input style="width: 50%;" type="text"/>
BradenHead			
Comment: <u>Bradenhead appears plumbed to surface.</u>	Corrective Action: <input style="width: 100%;" type="text"/>		Date: <input style="width: 50%;" type="text"/>

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691200845	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4655773