

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/26/2018

Submitted Date:

11/21/2018

Document Number:

688800349**FIELD INSPECTION FORM**

Loc ID _____ Inspector Name: _____ On-Site Inspection
Hughes, Jim _____ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 1375Name of Operator: LINDE INCAddress: 200 SOMERSET CORP BLVD #7000City: BRIDGEWATER State: NJ Zip: 07083**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments2 Number of Corrective Actions

-
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Pecor, John	970-385-1356	jpecor@blm.gov	
Hughes, Jerrod	970-565-7021	jerrod.hughes@linde.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
458267	SPILL OR RELEASE	AC	11/09/2018		-	Airco #2 Natural Gas Well	EI

General Comment:

On October 26, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Linde Inc. Airco #2 Natural Gas Well Spill/Release Point ID #458267. A Linde representative was on site during this field inspection. It was reported that the dump valve got stuck open and produced water overtopped the fiberglass tank. The location had been scraped of visually impacted material.

Inspected Facilities

Facility ID: 458267 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: PRODUCED WATER Estimated Spill Volume: _____

Comment: Please refer to Spill/Release Point ID #458267 in the COGIS database for more information regarding this release. Per COA on supplemental spill report document #401811750, the operator shall submit a Form 27 Site Investigation and Remediation Workplan.

Corrective Action: Contact COGCC EPS staff regarding Rule 906.c. Date: 11/26/2018

Reportable: YES GPS: Lat 37.352786 Long 108.782793

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Waste Management:

Type	Management	Condition	GPS (Lat)	(Long)	
	Piles	Inadequate			
Comment	Supplemental Spill Report #401811750 indicates that impacted material was stockpiled. Ensure that stockpiled material is contained within stormwater BMPs to prevent contaminant migration.				
Corrective Action	Provide waste transportation and final disposition information in accordance with 907.b.2 for all E&P waste transported off site.				Date: <u>12/03/2018</u>

Spill/Remediation:

Comment:

Corrective Action: Date: _____

Emission Control Burner (ECB): _____

Comment:

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

COGCC Comments

Comment	User	Date
<p>On October 26, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Linde Inc. Airco #2 Natural Gas Well Spill/Release Point ID #458267. A Linde representative was on site during this field inspection. It was reported that the dump valve got stuck open and produced water overtopped the fiberglass tank. The location had been scraped of visually impacted material.</p> <p>Provide waste transportation and final disposition information in accordance with 907.b.2 for all E&P waste transported off site.</p> <p>The flow path of the release followed a drainage feature to the edge of a sandstone cliff. A site map indicates that the release terminated within the dry drainage feature that continues below the cliff band.</p> <p>The operator shall provide a Form 27 Site Investigation and Remediation Workplan detailing ongoing and proposed remediation activities.</p>	hughesjo	11/21/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401848081	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4653031
688800350	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4653029