

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/26/2018

Submitted Date:

11/21/2018

Document Number:

688800353**FIELD INSPECTION FORM**Loc ID 313551 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 1375Name of Operator: LINDE INCAddress: 200 SOMERSET CORP BLVD #7000City: BRIDGEWATER State: NJ Zip: 07083**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hughes, Jerrod	970-565-7021	jerrod.hughes@linde.com	SW Inspection Reports
Pecor, John	970-385-1356	jpecor@blm.gov	
Fischer, Alex		alex.fischer@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
112976	PIT	AC			-	AIRCO DUDLEY 5	EI
224457	WELL	PR	11/30/2007	GW	083-06522	AIRCO DUDLEY 5	EI

General Comment:

On October 26, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Linde Inc. Airco Dudley #5. For the most recent field inspection report of this facility, please refer to document #685301848.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Free standing sign near well head.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Plant phone number listed on location sign. Linde representative answered call and stated that phone number is not manned 24/7.

Corrective Action: Install sign to comply with Rule 210.b.

Date: 12/21/2018

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Steel pipe barricade fence around well head.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Flow Line	# 1		
Comment:			
Corrective Action:		Date:	
Type: Dehydrator	# 1		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	<u>112976</u>	Type:	<u>PIT</u>	API Number:	<u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>EI</u>
Facility ID:	<u>224457</u>	Type:	<u>WELL</u>	API Number:	<u>083-06522</u>	Status:	<u>PR</u>	Insp. Status:	<u>EI</u>

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					
Compaction	Pass	Compaction	Pass			
Berms	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: YESPit ID: 112976Lat: 37.376428Long: -108.788487Reference Point: Other: Length: Width: **Lining:**Liner Type: PlasticLiner Condition: AdequateComment: Leak detection system between liners.Corrective Action Date: **Fencing:**Fencing Type: Netting/Fence comFencing Condition: AdequateComment: Corrective Action Date: **Netting:**Netting Type: Fence/Net ComboNetting Condition: GoodComment: Corrective Action Date: Anchor Trench Present: YESOil Accumulation: NO2+ feet Freeboard: YESComment: Corrective Action Date: **COGCC Comments**

Comment	User	Date
On October 26, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Linde Inc. Airco Dudley #5. For the most recent field inspection report of this facility, please refer to document #685301848. The location sign is missing emergency contact information and a 24 contact number for the operator.	hughesjo	11/21/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401848415	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4653552

688800354	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4653551
-----------	-------------------	---

