

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/28/2018

Submitted Date:

11/29/2018

Document Number:

694400063**FIELD INSPECTION FORM**Loc ID 333163 Inspector Name: Kraich, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 1801 CALIFORNIA STREET #2500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kraich, Adam	970-420-0536	Adam.Kraich@state.co.us	(Area 117) Field Operations
Adamczyk, Megan		megan.adamczyk@state.co.us	
,		Cogcc.inspections@crestonepr.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
333163	LOCATION	AC			-	Sullivan 26H-P268	AC

General Comment:

Inspected Facilities

Facility ID: 333163 Type: LOCATION API Number: - Status: AC Insp. Status: AC

Producing Well

Comment: AC

Inspection in resposne to complaint.

Corrective Action:

Date:

Complaint

Comment: Inspection in response to complaint. 18# 200446783

Field Inspector Assigned: Adam Kraich

Complaint Received:

Date: 11-28-2018

Complaint Contacted:

Date: 11-28-2018 @ 14:42

Location #: 333163

Inspection Document #: 694400063

Nature of complaint: Noise/lighting

Field Inspector Actions:

On 11-27-2018, I received a complaint in regard to noise, and lighting coming from the Sullivan 26H tank battery location.

On 11-28-2018, I performed a complete inspection of the location, in addition to performing a sound audit per rule 802.c (1).
The sound audit shows an LEQ average of 59.3 db average over the course of the audit.
See sound audit report attached to inspection document for details.

On 11-18-2018, I returned to the location post civil twilight, to inspect lighting complaint. I found no lights on the location, see photos attached to inspection document.

As the location is now in its production phase, it is determined to be out of compliance under rule 802.b. See inspection document for corrective action requirements.

All information reviewed and site inspection information were submitted to the complaint specialist for further review.

Corrective Action: Comply with rule 802, identify and install control measures.

Date: 12/01/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694400066	Sound Audit	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4658416
694400067	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4658417