

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/07/2018

Submitted Date:

11/29/2018

Document Number:

688800365**FIELD INSPECTION FORM**Loc ID 335964 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10091Name of Operator: BERRY PETROLEUM COMPANY LLCAddress: 5201 TRUXTUN AVENUE #100City: BAKERSFIELD State: CA Zip: 90339**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Arauza, Steven		steven.arauza@state.co.us	
Johnson, Derek	970-285-2200	djohnson@bry.com	Dist. Superintendent
Fischer, Alex		alex.fischer@state.co.us	
Wilbourn, Don		dwilbourn@bry.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449191	LAND APPLICATION SITE	AC	02/10/2017		-	I31 596 449191	EI

General Comment:

On November 7, 2018 COGCC Western Environmental Supervisor Alex Fischer, EPS staff Stan Spencer, Steven Arauza, and Jim Hughes conducted an environmental field inspection of the Berry I31 596 Land Application Site, Facility ID #449191. For the most recent field inspection report of this facility, please refer to document #688800197.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	OTHER		
Comment:	Free standing location sign near entrance to pad.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Posted on location sign.		
Corrective Action:		Date:	

Good Housekeeping:			
Type	DEBRIS		
Comment:	Continue to remove liner pieces as they become exposed.		
Corrective Action:		Date:	
Type	STORAGE OF SUPL		
Comment:	Sand bags are being stored in the secondary containment berm for the tank battery.		
Corrective Action:	Comply with Rule 603.f.	Date:	12/28/2018
Type	OTHER		
Comment:	PBV labeled 100 bbl. Water/Condensate is stained near thief hatch.		
Corrective Action:		Date:	

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Environmental**Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Drill Cuttings	Land Treatment	Adequate		
Comment	Please refer to REM #10241 in the COGIS database for more information regarding this remediation project. Final samples indicate that the material is compliant with Table 910-1, except for Arsenic. Documentation attached to Supplemental Form 27 #401854170 shows that native Arsenic concentrations typically exceed Table 910-1 standards.			
Corrective Action				Date: <input type="text"/>

Spill/Remediation:

Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: <input type="text"/>

Emission Control Burner (ECB):	<input type="text"/>
Comment:	<input type="text"/>
Pilot: <input type="text"/>	Wildlife Protection Devices (fired vessels): <input type="text"/>

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Pass	
				Self Inspection	Pass	

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	423715	1642034	
	423715	1642034	

COGCC Comments

Comment	User	Date
<p>On November 7, 2018 COGCC Western Environmental Supervisor Alex Fischer, EPS staff Stan Spencer, Steven Arauza, and Jim Hughes conducted an environmental field inspection of the Berry I31 596 Land Application Site, Facility ID #449191. For the most recent field inspection report of this facility, please refer to document #688800197.</p> <p>Confirmation sample results indicate that land farmed material is compliant with Table 910-1. Land farmed material will be spread out on the existing location. Rocks removed from land farm treatment cells will reportedly be used for armoring along berms, etc. REM #10241 has been closed in the COGIS database.</p> <p>During this inspection it was noted that the PBV labeled "100 bbl. Water/Condensate" is stained near the thief hatch. A tear was observed in the secondary containment berm liner. Ensure liner integrity.</p> <p>Sand bags are being stored in the secondary containment area for the tank battery. If not necessary for operations on this lease, have them removed.</p>	hughesjo	11/29/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800366	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4659231