

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/30/2018

Submitted Date:

11/30/2018

Document Number:

689302493

**FIELD INSPECTION FORM**

Loc ID 334787 Inspector Name: Holtz, Darin On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**  
 OGCC Operator Number: 10456  
 Name of Operator: CAERUS PICEANCE LLC  
 Address: 1001 17TH STREET #1600  
 City: DENVER State: CO Zip: 80202

**Findings:**  
7 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name | Phone | Email                                 | Comment                                  |
|--------------|-------|---------------------------------------|--|
| Elsener,     |       | COGCC.inspections@caerusoilandgas.com | <a href="#">all Piceance inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name              | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------------|-------------|
| 89040       | WELL | PR     | 04/27/2000  | GW         | 045-07368 | COUEY 17-12                | PR          |
| 275135      | WELL | PR     | 08/27/2005  | GW         | 045-13467 | COUEY 17-12A1 (317E)       | PR          |
| 275136      | WELL | PR     | 09/01/2005  | GW         | 045-13466 | COUEY 17-12C (L17E)        | PR          |
| 276869      | WELL | PR     | 08/15/2005  | GW         | 045-10544 | COUEY FEDERAL 17-13 (L17E) | PR          |
| 276870      | WELL | PR     | 07/01/2018  | GW         | 045-10545 | COUEY 18-9D (L17E)         | PR          |

**General Comment:**  
 This is a follow up inspection from [Doc# 689302200](#). Required Corrective Action (s) items noted in previous inspections have been satisfied.  
 Equipment inventory has not changed on location.  
 Location is snow covered.

| Inspected Facilities  |                                 |       |      |             |           |         |    |               |    |
|-----------------------|---------------------------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:          | 89040                           | Type: | WELL | API Number: | 045-07368 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                                 |       |      |             |           |         |    |               |    |
| Comment:              | Well Producing on plunger lift. |       |      |             |           |         |    |               |    |
| Corrective Action:    |                                 |       |      |             | Date:     |         |    |               |    |
| Facility ID:          | 275135                          | Type: | WELL | API Number: | 045-13467 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                                 |       |      |             |           |         |    |               |    |
| Comment:              | Well Producing on plunger lift. |       |      |             |           |         |    |               |    |
| Corrective Action:    |                                 |       |      |             | Date:     |         |    |               |    |
| Facility ID:          | 275136                          | Type: | WELL | API Number: | 045-13466 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                                 |       |      |             |           |         |    |               |    |
| Comment:              | Well Producing on plunger lift. |       |      |             |           |         |    |               |    |
| Corrective Action:    |                                 |       |      |             | Date:     |         |    |               |    |
| Facility ID:          | 276869                          | Type: | WELL | API Number: | 045-10544 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                                 |       |      |             |           |         |    |               |    |
| Comment:              | Well Producing on plunger lift. |       |      |             |           |         |    |               |    |
| Corrective Action:    |                                 |       |      |             | Date:     |         |    |               |    |
| Facility ID:          | 276870                          | Type: | WELL | API Number: | 045-10545 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                                 |       |      |             |           |         |    |               |    |
| Comment:              | Well Producing on plunger lift. |       |      |             |           |         |    |               |    |
| Corrective Action:    |                                 |       |      |             | Date:     |         |    |               |    |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                   | URL   |
|--------------|-------------------------------|---|
| 689302494    | Inspection photo<br>689302494 | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4661013">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4661013</a> |