

Inspection Photos

Operator: Petrox Resources

API: 05-007-06316

Date: 11/06/2018



Photo 1. View of the project area from the western corner facing center.



Photo 2. View of the western project area from the western corner facing southward. Some desirable vegetation is becoming established.



Photo 3. View of the northwestern project area from the western corner facing northeastward. Revegetation is sparse on this slope and needs to be monitored.



Photo 4. View of stormwater controls in the northeastern project area.



Photo 5. View of the southern project area from the southeastern corner facing southwestward.



Photo 6. View of unstabilized soils in the northern project area diversion that appear to be discharged from ditch excavation. Erosion control measures such as revegetation need to applied to loose, disturbed soils.