

Inspection Photo (s)
Savage 41A-8
API # 05-045-18560
Inspection # 689302497



Location Photo #1



Location Photo #2

Inspection Photo (s)
Savage 41A-8
API # 05-045-18560
Inspection # 689302497



2/03/18

Location Photo #3



2/03/18

**Location Photo #4, unused equipment on
North side of location.**

Inspection Photo (s)
Savage 41A-8
API # 05-045-18560
Inspection # 689302497




Location Photo #5, missing barrel capacity on all tanks within battery.



Location Photo #6, missing barrel capacity on all tanks within battery.

Inspection Photo (s)
Savage 41A-8
API # 05-045-18560
Inspection # 689302497



Location Photo #7, Missing information on 5 tanks in the battery.



Location Photo #8, Missing information on 5 tanks in the battery.

Inspection Photo (s)
Savage 41A-8
API # 05-045-18560
Inspection # 689302497



Location Photo #9, Missing information on 5 tanks in the battery.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photo (s)
Savage 41A-8
API # 05-045-18560
Inspection # 689302497



Location Photo #10, Unmarked flow lines



Location Photo #11, Unmarked flow lines

Inspection Photo (s)
Savage 41A-8
API # 05-045-18560
Inspection # 689302497



2/03/18

Location Photo #12, unmarked flow line.



2/03/18

Location Photo #13, Unused 500 bbl frac tank.

Inspection Photo (s)
Savage 41A-8
API # 05-045-18560
Inspection # 689302497



Location Photo #14, unused pipe on East side of battery containment.



Location Photo #15, Cable restraints on East corner of battery containment.