

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

12/05/2018

Submitted Date:

12/05/2018

Document Number:

694400068**FIELD INSPECTION FORM**
 Loc ID 455340 Inspector Name: Kraich, Adam On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10459Name of Operator: EXTRACTION OIL & GAS INCAddress: 370 17TH STREET SUITE 5300City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|-------|---------------------------------------|---------------------------------|
| Leonard, Mike | | mike.leonard@state.co.us | |
| , | | COGCCInspections@extracti onog.com | All Inspections |
| Adamczyk, Megan | | megan.adamczyk@state.co.u s | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------------|-------------|
| 456277 | WELL | DG | 08/30/2018 | | 123-47481 | Rinn Valley West 18N-25-04N | DG |

General Comment:

Inspected FacilitiesFacility ID: 456277 Type: WELL API Number: 123-47481 Status: DG Insp. Status: DG**Complaint**Comment: Inspection in response to complaint. 18# 200446790Field Inspector Assigned: Adam KraichComplaint Received:Date: 12-5-2018Complaint Contacted:Date: 12-5-2018 N/ALocation #: 455340Inspection Document #: 694400068Nature of complaint: Odor/Air Quality.Field Inspector Actions:On 12-5-2018, I received a complaint in regard to odor, suspected to be coming from the Rinn Valley West location, owned and operated by Extraction Oil & Gas.On 12-5-2018, I performed an inspection of the location, as well as off location. Coil tubing was in drill out operations at the time of inspection. No wells are currently flowing back, nor have there been. Wells are shut in post drill out.No odors were observed off location at time of inspection.All information reviewed and site inspection information were submitted to the complaint specialist for further review.

Corrective Action:

Date:

CompletionOperation: Drillout

Date Flowback:

Contractor: PatriotComment: Inspection in response to complaint.

Corrective Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 694400069 | Inspection photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4664899 |