

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/28/2018

Submitted Date:

11/29/2018

Document Number:

694400063**FIELD INSPECTION FORM**Loc ID 333163 Inspector Name: Kraich, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 1801 CALIFORNIA STREET #2500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|-----------------|--------------|----------------------------------|-----------------------------|
| Adamczyk, Megan | | megan.adamczyk@state.co.us | |
| , | | Cogcc.inspections@crestonepr.com | |
| Kraich, Adam | 970-420-0536 | Adam.Kraich@state.co.us | (Area 117) Field Operations |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|----------|--------|-------------|------------|---------|-------------------|-------------|
| 333163 | LOCATION | AC | | | - | Sullivan 26H-P268 | AC |

General Comment:

Inspected FacilitiesFacility ID: 333163 Type: LOCATION API Number: - Status: AC Insp. Status: AC**Producing Well**Comment: ACInspection in resposne to complaint.

Corrective Action:

Date:

ComplaintComment: Inspection in response to complaint. 18# 200446783Field Inspector Assigned: Adam KraichComplaint Received:Date: 11-28-2018Complaint Contacted:Date: 11-28-2018 @ 14:42Location #: 333163Inspection Document #: 694400063Nature of complaint: Noise/lightingField Inspector Actions:On 11-27-2018, I received a complaint in regard to noise, and lighting coming from the Sullivan 26H tank battery location.On 11-28-2018, I performed a complete inspection of the location, in addition to performing a sound audit per rule 802.c (1). The sound audit shows an LEQ average of 59.3 db average over the course of the audit. See sound audit report attached to inspection document for details.On 11-18-2018, I returned to the location post civil twilight, to inspect lighting complaint. I found no lights on the location, see photos attached to inspection document.As the location is now in its production phase, it is determined to be out of compliance under rule 802.b. See inspection document for corrective action requirements.All information reviewed and site inspection information were submitted to the complaint specialist for further review.Corrective Action: Comply with rule 802, identify and install control measures.Date: 12/01/2018**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 401854174 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4658418 |
| 694400066 | Sound Audit | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4658416 |
| 694400067 | Inspection photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4658417 |