

Inspection Photos

Operator: BP Production

API: 05-067-09267

Date: 11/9/2018



Photo 1. View of the project area from the northwestern edge facing center.



Photo 2. View of the northern project area from the northwestern corner facing southeastward. Revegetation is progressing with grasses such as intermediate wheatgrass (*Thinopyron intermedium*), and crested wheatgrass (*Agropyron cristatum*).



Photo 3. View of the western project area from the northwestern corner facing southwestward.



Photo 4. View of the southwestern project area from the southwestern corner facing southeastward. Irrigation ditch runs adjacent to southern and eastern edges of the project area.



Photo 5. View of cobble rundown in the southwestern project area appears to be functioning at this time, but may soon require maintenance. Approximately 500 Canada thistles (visible in the cobble in the foreground) are growing within the southern interim reclamation areas.