

# Inspection Photos

Operator: BP Production

API: 05-067-06657

Date: 11/9/2018



**Photo 1. View of the project area from the southwestern corner facing center.**





**Photo 2.** View of the southern project area from the southwestern corner facing eastward. Revegetation is progressing here with western wheatgrass (*Pascopyrum smithii*), sand dropseed (*Sporobolus cryptandrus*), and rubber rabbitbrush (*Chrysothamnus nauseosus*).





**Photo 3. View of the western project area from the southwestern corner facing westward.**





**Photo 5. View of erosional channeling occurring within the western project area.**





**Photo 5. View of erosional channel approximately 1.5 feet wide and 10 inches deep, forming within the northern project area around project facilities.**





**Photo 5. View of erosional channel along the access road.**





**Photo 5. View of kochia debris up to 2.5 feet high, at the well pad entrance and along the access road.**