

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/07/2018

Submitted Date:

11/30/2018

Document Number:

688800369**FIELD INSPECTION FORM**
 Loc ID 335658 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10091Name of Operator: BERRY PETROLEUM COMPANY LLCAddress: 5201 TRUXTUN AVENUE #100City: BAKERSFIELD State: CA Zip: 90339**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Wilbourn, Don		dwilbourn@bry.com	
Arauzo, Steven		steven.arauza@state.co.us	
Johnson, Derek	970-285-2200	djohnson@bry.com	Dist. Superintendent
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
443325	LAND APPLICATION SITE	AC	09/25/2015		-	Chevron 036B 596	EI

General Comment:

On November 7, 2018 COGCC Western Environmental Supervisor Alex Fischer, and EPS staff members Stan Spencer, Steven Arauzo, and Jim Hughes conducted an environmental field inspection of the Berry Chevron 036B 596 Land Application Site, Facility ID #443325. For the most recent field inspection report of this facility, please refer to document #688800199. Berry representatives Derek Johnson and Don Wilbourn were on site during this inspection.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	OTHER		
Comment:	Free standing sign near location entrance.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Posted on location sign.		
Corrective Action:		Date:	

Good Housekeeping:

Type	DEBRIS		
Comment:	Continue to remove liner pieces as they become exposed.		
Corrective Action:		Date:	
Type	UNUSED EQUIPMENT		
Comment:	Joints of unused steel pipe stored in secondary containment berm.		
Corrective Action:	Comply with Rule 603.f.	Date:	12/31/2018

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	443325	Type:	LAND	API Number:	-	Status:	AC	Insp. Status:	EI

--

Environmental**Waste Management:**

Type	Management	Condition	GPS (Lat) (Long)	
Drill Cuttings	Land Treatment	Adequate		
Comment	Please refer to REM #10236 for more information regarding this remediation project.			
Corrective Action				Date:

Spill/Remediation:

Comment:			
Corrective Action:		Date:	

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Pass	
				Self Inspection	Pass	

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>On November 7, 2018 COGCC Western Environmental Supervisor Alex Fischer, and EPS staff members Stan Spencer, Steven Arauza, and Jim Hughes conducted an environmental field inspection of the Berry Chevron O36B 596 Land Application Site, Facility ID #443325. For the most recent field inspection report of this facility, please refer to document #688800199. Berry representatives Derek Johnson and Don Wilbourn were on site during this inspection.</p> <p>Compliant material has been moved from the eastern portion of the location to the pit area, to allow for spreading of more material from the western edge of the location.</p> <p>Continue to remove liner pieces from land farm as they become exposed.</p> <p>Steel pipe joints observed in secondary containment berm during this inspection. If these are not necessary for operations at this location, they need to be removed.</p>	hughesjo	11/30/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401856978	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4660949
688800370	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4660947