

Inspection Photos
Location Name: Kelsall 33-7 #4-1
API: 05-067-09866



Horizontal heated separators for wells #4-1 through #4-4.



2 - 300 bbl. produced water ASTs.

Inspection Photos
Location Name: Kelsall 33-7 #4-1
API: 05-067-09866



#4-3 and #4-4 well heads. Pump jack on #4-3 was dismantled at the time of this inspection.



#4-1 and #4-2 well heads and pump jacks.

Inspection Photos
Location Name: Kelsall 33-7 #4-1
API: 05-067-09866



Lube oil leak underneath prime mover on #4-3.



Stained soil at #4-2 well head.

Inspection Photos
Location Name: Kelsall 33-7 #4-1
API: 05-067-09866



Stained soil at #4-1 well head.



Unused equipment and containers stored at base of pump jack.

Inspection Photos
Location Name: Kellsall 33-7 #4-1
API: 05-067-09866



Stained soil at exhaust for prime mover.



Meter shacks adjacent to location.