

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/21/2018

Submitted Date:

11/21/2018

Document Number:

693200185**FIELD INSPECTION FORM**Loc ID 335404 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1400City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Colby, Lou	970-989-4402	lou.colby@state.co.us	Area Reclamation Specialist
Bankert, Wayne	(970) 683-5419	cogccnotifications@laramie-energy.com	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256360	WELL	PR	02/15/2004	GW	045-07450	CASCADE CREEK 617-24	EG
277265	WELL	PR	10/20/2014	GW	045-10652	CASCADE CREEK 697-17-43D	EG
277297	WELL	PR	05/28/2006	GW	045-10663	CASCADE CREEK 697-20-02D	EG
277330	WELL	PR	06/05/2006	GW	045-10673	CASCADE CREEK 697-17-49D	EG
277331	WELL	PR	05/13/2013	GW	045-10674	CASCADE CREEK 697-17-53D	EG
277334	WELL	PR	08/01/2012	GW	045-10677	CASCADE CREEK 697-20-05D	EG

General Comment:[Engineering Integrity Inspection,](#)[Lou Colby copied on inspection due to flowline trench not being reclaimed and sediment movement down hillside, See photo's](#)

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	2 - 8" poly flow lines open to atmosphere, West side of location		
Corrective Action:	For unused , unmarked flowline risers 24 hrs to lock out tag out. 30 days to remove riser.		Date: 12/21/2018
Type	UNUSED EQUIPMENT		
Comment:	2 - 2" Steel flow lines behind separators		
Corrective Action:	For unused , unmarked flowline risers 24 hrs to lock out tag out. 30 days to remove riser.		Date: 12/21/2018

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: <u>256360</u>	Type: <u>WELL</u>	API Number: <u>045-07450</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>277265</u>	Type: <u>WELL</u>	API Number: <u>045-10652</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>277297</u>	Type: <u>WELL</u>	API Number: <u>045-10663</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>277330</u>	Type: <u>WELL</u>	API Number: <u>045-10673</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>277331</u>	Type: <u>WELL</u>	API Number: <u>045-10674</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>277334</u>	Type: <u>WELL</u>	API Number: <u>045-10677</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401848351	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4653443
693200189	laramie	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4653441