

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/29/2018

Submitted Date:

12/04/2018

Document Number:

679300021**FIELD INSPECTION FORM**Loc ID 306735 Inspector Name: Graber, Candice (Nikki) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
Longhurst, Mark		Mark.Longhurst@pdce.com	
Oakman, Kari		kari.oakman@state.co.us	
Inspections, All		cogccinspection@pdce.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290623	WELL	SI	07/01/2018	OW	123-25173	VIEFHAUS 43-29U	EI

**General Comment:**

COGCC inspection of produced water vault removal pursuant to the Matt #1 Administrative Order on Consent (AOC) order no. 1V-678 item #6. PDC notified COGCC of planned start date of 11/26/2018, inspection occurred on 11/29/2018, there were no operator or contract environmental personnel on location at the time. Vault and all other equipment had been removed and hauled from location area has been graded and is ready for reclamation



**Environmental****Spill/Remediation:**

Comment: Produced water vault removed. ite has been backfilled, no oily waste stockpiled on location.

Corrective Action: The Operator shall submit a Form 27 Site Investigation and Remediation Workplan for the removal of a buried/partially buried produced water vessel in accordance with Rule 905.b. The Form 27 Workplan may be submitted with the excavation and site assessment results, but should be submitted no later than 90 days from the Spill Report Date in order to resolve this release.

Date: 02/27/2019

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401860503	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4664220">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4664220</a>
679300022	Site Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4664212">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4664212</a>