

Inspection Photos

Location Name: Pond 10 Centralized E&P Waste Management Facility

Facility ID: #159504 Pit Facility ID: #291946

Inspection Date: November 28, 2018



Photo #1 – Sign located at SE corner of pit.



Photo #2 – Inlets to Pond 10 pit located on south side.



Inspection Photos

Location Name: Pond 10 Centralized E&P Waste Management Facility

Facility ID: #159504 Pit Facility ID: #291946

Inspection Date: November 28, 2018



Photo #3 – Wildlife netting over top of Pond 10 pit has been removed for the winter months, per agreement between operator and CPW.



Photo #4 – Maintenance required at several netting posts along west side of pit (1).



Inspection Photos

Location Name: Pond 10 Centralized E&P Waste Management Facility

Facility ID: #159504 Pit Facility ID: #291946

Inspection Date: November 28, 2018



Photo #5 - Maintenance required at several netting posts along west side of pit (2).



Photo #6 – Unused equipment (steel cable) stored on west side of pit, in contact with pit liner.

Inspection Photos

Location Name: Pond 10 Centralized E&P Waste Management Facility

Facility ID: #159504 Pit Facility ID: #291946

Inspection Date: November 28, 2018



Photo #7 - Unused equipment (chain link) stored on north side of pit.



Photo #8 – Foreign material (sand bag remnants) on top of liner on east side of pit.

Inspection Photos

Location Name: Pond 10 Centralized E&P Waste Management Facility

Facility ID: #159504 Pit Facility ID: #291946

Inspection Date: November 28, 2018



Photo #9 – View of 400 bbl fresh water ASTs from north. Tan ASTs in foreground are visible in COGCC GIS Online 2017 Aerial photographs. Black ASTs in background are not.



Photo #10 – View of south tank battery from NW corner. Most of these LTR tanks were labelled “Fresh Water” on inspection date.



Inspection Photos

Location Name: Pond 10 Centralized E&P Waste Management Facility

Facility ID: #159504 Pit Facility ID: #291946

Inspection Date: November 28, 2018



Photo #11 – View of south tank battery from SE corner. Note absence of earthen berm along east side of tank battery.



Photo #12 – One of several tanks in south tank battery that was labelled “Produced Water.” These tanks did not appear to be in use on inspection date, many were labelled “Do not use”.