

Inspection Photos

12/12/2018

Operator: PHOENIX RESOURCES LLC - 10691

Location ID: 414589

Inspection Doc. Number: 682504271

Lincoln County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the west end of the location. Previous inspections documented this 5 gallon bucket being used to collect chemicals from equipment and stained soils at the base. Inspections required that equipment needs to be repaired to fix leaks, and bucket needs to be removed and properly disposed or placed in containment. Photo shows bucket and stained soils remain.



Photo 2: See comment under photo 1.



Photo 3: Photo taken from the west end of the location facing west. Photo shows stained soil and a bucket with various contaminated soils without secondary containment.



Photo 4: Photo taken from the west end of the location facing west. Photo shows stained soil and a bucket with various contaminated soils without secondary containment.




Photo 5: Photo taken from the west end of the production area, facing north. Photo of pump unit.

Inspection Photos
Operator: PHOENIX RESOURCES LLC - 10691
Location ID: 414589



Photo 6: Photo taken from the southeast end of the pump jack, facing northwest. Previous inspections documented numerous 5 gallon buckets w/ chemical and oil jugs found around pump jack, and required containers to be properly removed and disposed, or placed into containment. Photo shows containers have not been removed or placed into containment.



Photo 7: Photo taken from the east end of the pump jack, facing west. Previous inspections documented numerous 5 gallon buckets w/ chemical and oil jugs found around pump jack, and required containers to be properly removed and disposed, or placed into containment. Photo shows containers have not been removed or placed into containment.



Photo 8: See comments under photo 7



Photo 9: Photo taken from the east end of the pump, facing northwest. Photo shows unused equipment stored on location and a 5 gallon buckets w/ contaminated material. Previous inspections documented required equipment not needed for production needs to be removed, and containers placed within secondary containment.



Photo 10: Continued from photo 9. Photo shows bucket with contaminated materials.



Photo 11: Photo taken from the north end of the well, facing south. Previous inspections documented contaminated soils around well and required stained soils to be cleaned. Photo shows contaminated soils remain.



Photo 12: Photo taken from the north end of the well, facing west. Previous inspections documented contaminated soils around well and required stained soils to be cleaned. Photo shows contaminated soils remain.



Photo 13: Photo taken from the north end of the well, facing south. Photo shows unused equipment not needed for production remains on location.



Photo 14: Photo taken from the north end of the location, facing northwest. Previous inspections required contaminated soils to be removed. Photo shows soils remain.



Photo 15: Photo taken from the north end of the location, facing southwest. Photo shows unused equipment not needed for production remains on location.

Inspection Photos
Operator: PHOENIX RESOURCES LLC - 10691
Location ID: 414589



Photo 16: Photo taken from the north end of the location, facing southwest. Photo shows unused equipment not needed for production, and various trash debris remains on location.

Inspection Photos
Operator: PHOENIX RESOURCES LLC - 10691
Location ID: 414589



Photo 17: Photo taken from the north end of the location, facing north. Photo shows unused equipment not needed for production remains on location.



Photo 18: Photo taken from the north end of the location, facing north. Previous inspection documented camper trailer being stored on location. Trailer is not needed for production and was required to be removed. Camper trailer remains. Photo also shows various trash debris around camper trailer.



Photo 19: Photo taken from the north end of the location, facing southwest. Photo shows various unused equipment not needed for production remains stored on location.



Photo 20: Photo taken from the north end of the location, facing southwest. Photo shows various unused equipment not needed for production remains stored on location.



Photo 21: Photo taken from the north end of the location, facing southwest. Photo shows trash debris remains on location.



Photo 22: Photo taken from the north end of the location, facing west. Photo shows various unused equipment not needed for production remains stored on location



Photo 23: Photo taken from the north end of the location, facing west. Photo shows various unused equipment not needed for production, and trash debris remains stored on location.



Photo 24: Photo taken from the north end of the location. Previous inspections documented 5 gallon buckets w/ chemical and stained soils and required buckets to be properly removed and disposed, or placed into containment and soil cleaned. Photo shows buckets and contaminated soils remain.



Photo 25: Photo taken from the north end of the location. Previous inspections documented 5 gallon buckets w/ chemical and stained soils and required buckets to be properly removed and disposed, or placed into containment and soil cleaned. Photo shows buckets and contaminated soils remain.

Inspection Photos
Operator: PHOENIX RESOURCES LLC - 10691
Location ID: 414589



Photo 26: Photo taken from the northeast corner of the tank battery, facing south. Previous inspections required operator to remove vegetation from the berms of the battery and production equipment; vegetation compromises the integrity of the containment berms. Photo shows vegetation has not been removed.



Photo 27: Photo taken from the south end of the location, facing south. Photo shows what appears to be four (4) bundles of pipe stored on the southern interim area. Previous inspections documented that this is unused equipment not needed for production and that needs to be removed from location. Photo shows equipment has not been removed.



Photo 28: Photo taken from the south end of the location, facing south. Photo shows what appears to be four (4) bundles of pipe stored on the southern interim area. Previous inspections documented that this is unused equipment not needed for production and that needs to be removed from location. Photo shows equipment has not been removed.



Photo 29: Photo taken from the west end of the tank battery. Previous inspections documented stained soils within the berm, and that the manway cover has been removed from the tank. Photo shows cover has not been replaced and stained soils remain