

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/12/2018

Submitted Date:

12/13/2018

Document Number:

688303176**FIELD INSPECTION FORM**
 Loc ID 322162 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 74165Name of Operator: RENEGADE OIL & GAS COMPANY LLCAddress: 6155 S MAIN STREET #210City: AURORA State: CO Zip: 80016**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:16 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Condill, JB	303-680-4725	jbcrog@aol.com	All Inspections
Ingve, Ed	303-829-2354	ed@renegadeoilandgas.com	All Inspections
Espinosa, Bill	(303) 829-4982	billespinosa30@yahoo.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
209429	WELL	PR	12/20/1996	OW	039-06334	CHAMPLIN 416 AMOCO C 1	PR

General Comment:[Reinspection. Corrective action from previous inspection are completed.](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	sign ripped in half but tank battery is on same pad location, fix sign or remove		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 303-680-4725

Corrective Action:

Date: _____

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	barbed wire		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	barbed wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	barbed wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:	chemical container		
Corrective Action:		Date:	
Type: Pump Jack	# 1		

Comment:		Date:	
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	LO/TO	Date:	
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	gas engine, shed, oil from engine spilled on concrete pad (see attached photo), inspector contacted operator who will clean it up right away	Date:	
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:		Date:	
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	replace wire mesh cover over bird protector on separator (see attached photo) that was blown off	Date:	
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	80 bbls
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	same berms as crude oil tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					
Corrective Action:					
Corrective Action:					

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Inspector Name: Sherman, Susan

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	209429	Type:	WELL	API Number:	039-06334	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR. Sep 2018 production reported to COGCC database.								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	
Other	Pass					caps on pipe ends

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688303206	Renegade Champlin 416 Amoco C 1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4675814