

FORM  
INSPRev  
X/15

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/05/2018

Submitted Date:

12/07/2018

Document Number:

688800383**FIELD INSPECTION FORM**

Loc ID 424701 Inspector Name: Hughes, Jim On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 34725  
Name of Operator: GOSNEY & SONS INC  
Address: P O BOX 367  
City: BAYFIELD State: CO Zip: 81122

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 21 Number of Comments  
4 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Barnett, Matt		mattb@gosneyco.com	
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
424697	WELL	PR	06/01/2012	GW	067-09866	KELSALL 33-7 4-1	EI
428042	WELL	PR	06/01/2013	GW	067-09880	KELSALL 33-7 4-4	EI
428043	WELL	PR	10/02/2012	GW	067-09881	KELSALL 33-7 4-2	EI
428044	WELL	PR	05/29/2013	GW	067-09882	KELSALL 33-7 4-3	EI

**General Comment:**

On December 5, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Gosney and Sons Inc. Kelsall 33-7 #4-1. For the most recent field inspection report of this facility, please refer to document #685302912.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L		Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Tank battery sign mounted to handrail on stairs.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Well head number stenciled on each well head.		
Corrective Action:			Date:
Type	OTHER		
Comment:	Well signs mounted to separator buildings.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Tanks have labels and placards.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Posted on location signs.		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	STORAGE OF SUPL		
Comment:	Oil containers, pipes, and fittings stored at pump jacks.		
Corrective Action:	Comply with Rule 603.f.		Date: 01/07/2019
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
Lube Oil	WELLHEAD	<= 1 bbl	
Comment:	Stained soil around base of #4-1 and #4-2 wellheads.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date: 01/07/2019
Lube Oil	Pump Jack	<= 1 bbl	
Comment:	Stained soil near prime mover exhaust.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date: 01/07/2019
Lube Oil	Pump Jack	<= 1 bbl	
Comment:	Lube oil leak below prime mover on #4-3 pump jack.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date: 01/07/2019

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	SEPARATOR		
Comment:	Jersey barriers next to separators.		
Corrective Action:			Date:
Type	LOCATION		
Comment:	Perimeter fencing w/ cattle gaurd.		
Corrective Action:			Date:

**Equipment:**

			corrective date
Type: Prime Mover	# 3		
Comment:	Natural gas engines.		
Corrective Action:			Date:
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 4		
Comment:	Telemetry equipment		
Corrective Action:			Date:
Type: Flow Line	# 4		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 4		
Comment:	Two steel buildings with two separators each.		
Corrective Action:			Date:
Type: Plunger Lift	# 2		
Comment:	#4-3 and #4-4 wells.		
Corrective Action:			Date:
Type: Pump Jack	# 3		
Comment:	#4-3 pump jack was dismantled during this inspection.		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	HEATED STEEL AST		37.136842,-107.613934
Comment:	Northern AST.				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	

Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:	
Corrective Action:	Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		37.136797,-107.613936

Comment: <a href="#">Southern AST.</a>	
Corrective Action:	Date:

**Paint**

Condition	Adequate	
-----------	----------	--

Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:	
Corrective Action:	Date:

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 424697 Type: WELL API Number: 067-09866 Status: PR Insp. Status: EI

Facility ID: 428042 Type: WELL API Number: 067-09880 Status: PR Insp. Status: EI

Facility ID: 428043 Type: WELL API Number: 067-09881 Status: PR Insp. Status: EI

Facility ID: 428044 Type: WELL API Number: 067-09882 Status: PR Insp. Status: EI

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap	Pass					
Berms	Pass	Gravel	Pass			
Compaction	Pass	Culverts	Pass	Material Handling And Spill Prevention	Pass	Drip pot at truck load out.
Gravel	Pass					
Ditches	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
On December 5, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Gosney and Sons Inc. Kelsall 33-7 #4-1. For the most recent field inspection report of this facility, please refer to document #685302912. Similar issues with stained soil and storage of containers were noted on inspection document #685302440.	hughesjo	12/07/2018

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401865748	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4668069">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4668069</a>
688800384	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4668065">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4668065</a>