

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/12/2018

Submitted Date:

12/14/2018

Document Number:

688800397**FIELD INSPECTION FORM**

Loc ID _____ Inspector Name: _____ On-Site Inspection
Hughes, Jim _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10000
 Name of Operator: BP AMERICA PRODUCTION COMPANY
 Address: 380 AIRPORT RD
 City: DURANGO State: CO Zip: 81303

Findings:

- 8 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports
Murray, Richard		g.richard.murray@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Baca, Matthew		matthew.baca@bpx.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
459307	SPILL OR RELEASE	AC	12/10/2018		-	Richardson G 2	EI

General Comment:

[On December 12, 2018 COGCC SW EPS Jim Hughes conducted a follow up environmental field inspection of the BP Richardson G #2 Spill/Release Point ID #459307. For the most recent field inspection report of this facility, please refer to document #688800387.](#)

Location

Lease Road:			
	Type	Access	
	comment:	Dirt and gravel access road. Release occurred near pipeline road crossing.	
	Corrective Action:		Date:

Overall Good:

Signs/Marker:			
	Type	OTHER	
	Comment:	Carsonite pipeline markers indicate pipelines cross access road near release point.	
	Corrective Action:		Date:

Emergency Contact Number:			
	Comment:	<input type="text"/>	
	Corrective Action:	<input type="text"/>	Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
	Type	OTHER	
	Comment:	Safety fencing present around excavation on east side of access road at the time of this inspection.	
	Corrective Action:		Date:

Venting:			
	Yes/No		
	Comment:		
	Corrective Action:		Date:

Flaring:			
	Type		
	Comment:		
	Corrective Action:		Date:

Inspected Facilities

Facility ID: 459307 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: PRODUCED WATER Estimated Spill Volume: 60

Comment: Please refer to Initial Spill/Release Report Document #401866521 for more information regarding this release.

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff. Date: 01/11/2019

Reportable: YES GPS: Lat 37.238919 Long -107.697998

Proximity to Surface Water: 500 Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

COGCC Comments

Comment	User	Date
<p>On December 12, 2018 COGCC SW EPS Jim Hughes conducted a follow up environmental field inspection of the BP Richardson G #2 Spill/Release Point ID #459307. For the most recent field inspection report of this facility, please refer to document #688800387. BP representative Jeff Davis was on site during this field inspection.</p> <p>During this inspection it was observed that the 3" fiberglass lines had been exposed with a hydro vac truck. There is a 12" steel casing sleeve at the road crossing. The fiberglass lines appear to come out of the casing sleeve at a downward angle. It was reported that when the release was discovered, fluid was coming out of the casing vent. Once the casing sleeve was exposed, fluid reportedly came out of it.</p> <p>A Williams pipeline running perpendicular to the BP gathering lines has been potholed in preparation of mechanical excavation of the fiberglass lines to expose the nearest pipe joint. A crew was preparing to expose the fiberglass lines on the western edge of the roadway.</p>	hughesjo	12/14/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800398	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4676455