

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/17/2018

Submitted Date:

12/17/2018

Document Number:

689302655

FIELD INSPECTION FORM

Loc ID 335185 Inspector Name: Holtz, Darin On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10531
Name of Operator: VANGUARD OPERATING LLC
Address: 5847 SAN FELIPE #3000
City: HOUSTON State: TX Zip: 77057

Findings:

- 19 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Aaron, Axelson	230-0926	aaxelson@vnrenergy.com	Sr. Production Foreman
Ghan, Scott	970-744-8128	sghan@vnrenergy.com	SR. EH&S
Collett, Shane		scollett@vnrenergy.com	Superintendent operations

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210958	WELL	PR	08/18/1995	GW	045-06716	JOLLEY 20-6 1	PR
289479	WELL	PR	08/04/2009	GW	045-13772	GGU JOLLEY 44C-20-691	PR
289480	WELL	PR	06/29/2007	GW	045-13771	GGU JOLLEY 44A-20-691	PR
289777	WELL	PR	07/16/2009	GW	045-13881	GGU JOLLEY 43B-20-691	PR
289778	WELL	PR	07/07/2007	GW	045-13880	GGU JOLLEY 43D-20-691	PR

General Comment:

[Routine Field Inspection.](#)

Location

Lease Road:			
Type	Access		
comment:	Access road snow covered.		
Corrective ActionL		Date:	

Overall Good:

Emergency Contact Number:			
Comment:	1-800-921-8252		
Corrective Action:		Date:	

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unmarked flowlines at separator and within the tank batttery, see photos		
Corrective Action:	Comply with Rule 603.f . For unused , unmarked flowline risers 24 hrs to lock out tag out. 30 days to remove riser, Mark as required.	Date:	04/17/2019

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Hog panel fence.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Panel gates.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panel fence.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 5		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			

Corrective Action:		Date:	
Type: Plunger Lift	# 5		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical unit at wellhead		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	300 BBLs	STEEL AST		,
Comment:	4 tanks in a centralized battery. 1 heated tank.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	YES
Comment:	Bradenhead valves open to vent.
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	210958	Type:	WELL	API Number:	045-06716	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	289479	Type:	WELL	API Number:	045-13772	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	289480	Type:	WELL	API Number:	045-13771	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	289777	Type:	WELL	API Number:	045-13881	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	289778	Type:	WELL	API Number:	045-13880	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
Berms						

Comment: [Location snow covered.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	301699	1433938	
	301699	1433938	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689302666	Inspection photo 689302266	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4679977