

# Interim Reclamation and Stormwater Inspection

December 14, 2018

Operator: ENERPLUS RESOURCES (USA) CORPORATION - #10177

Location ID: 450827

Inspection Document #: 682404262

Weld County, CO

SWSE Section 26 T8N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: IRISH PAD  
Location ID: 450827



**Photo 1.** Photo taken from the southern southern topsoil stockpile, facing East. Operator has failed to prevent weed establishment on the topsoil stockpile. Note: Appears the Operator attempted to seed the topsoil with desirable vegetation (e.g., blue grama) but weedy, annual vegetation (Kochia) was observed throughout most of the stockpile fill slope areas. Note: Kochia was observed throughout cut and fill slopes of the well pad.



**Photo 2.** Photo taken from the southern southern topsoil stockpile, facing West. See comments under Photo 1.

Inspection Photos  
Location Name: IRISH PAD  
Location ID: 450827



**Photo 3.** Photo taken from the southwestern perimeter of the location, facing West. Operator has failed to control and manage weedy, annual vegetation (Kochia).



**Photo 4.** Photo taken from the southwestern perimeter of the location, facing North. See comments under Photo 3.

Inspection Photos  
Location Name: IRISH PAD  
Location ID: 450827



**Photo 5.** Photo taken from the southwestern perimeter of the location, facing Southwest. Silt fence BMP in need of maintenance.



**Photo 6.** Photo taken from the entrance of the location, facing East. Photo illustrates unmanaged Kochia weeds along the cut slope.

Inspection Photos  
Location Name: IRISH PAD  
Location ID: 450827



**Photo 7.** Photo taken from the entrance of the location, facing West. See comments under Photo 6.