

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/10/2018

Submitted Date:

12/11/2018

Document Number:

679300053**FIELD INSPECTION FORM**
 Loc ID 318333 Inspector Name: Graber, Candice (Nikki) On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, All		NBL_DJBU_Inspections@NB LENERGY.COM	
Evans, Jacob		jacob.evans@nblenergy.com	
MacLaren, Joe		joe.maclaren@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241125	WELL	PR	04/14/2014	GW	123-08913	EDWARD HEMPLE UNIT 1	EI

**General Comment:**

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable. Photos attached to document site condition at the time of inspection.

COGCC Inspection in response to spill Document #401864473 reported by Operator. Excavation crew was awaiting environmental personnel to conduct sampling before continuing work.

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	241125	Type:	WELL	API Number:	123-08913	Status:	PR	Insp. Status:	EI

--

**Environmental****Spills/Releases:**

Type of Spill: OIL

Estimated Spill Volume: \_\_\_\_\_

Comment: Damaged flowline observed in excavation.

Corrective Action: On the next Form 19 subsequent operator is to provide the root cause of the incident and preventative measures that will be taken to prevent reoccurrence on this and other dump lines at this location. Please give the location of the failure (i.e. 6 O'clock position) and if the root cause is corrosion explain if it is external or internal. Please also list the wells associated with this facility on the Form 19 subsequent.

Date: 03/05/2019

Reportable: YES

GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401870945	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4672927">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4672927</a>
679300054	Location Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4672905">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4672905</a>