

Location

Lease Road:			
Type	Access		
comment:	BLM		
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Equipment:			corrective date
Type: Flow Line	#		
Comment:	Flowline riser locked out/tagged out. CA on inspection doc#680402290 completed. FIRR doc#401497480 submitted 12/28/2017.		
Corrective Action:			Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 221432 Type: WELL API Number: 077-08032 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well shut in pre 1999.
No current MIT on record or delinquent as required by Rule 326.
CA noted on inspection doc# completed. FIRR doc#401497480 submitted 12/28/2017.

Corrective Action: Contact dnr_cogccengineering@state.co.us with resolution plan. Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401870510	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4672561
680404084	Inspection photos 12/11/2018	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4672506