

Environmental

Spills/Releases:

Type of Spill: PRODUCED WATER Estimated Spill Volume: 60

Comment: Inspection to assess impact of Spill#459033. Sunny, 40F, no wind. ~14 bbl into lined SPCC for tank battery. ~45 bbl onto surface east of battery. ~50 bbl recovered w vac truck. Soil has been excavated to ~1 ft bgs in area east of tank battery. Soils are stockpiled on bermed HDPE liner.

Corrective Action: PER F-19 COA: Assess nature and extent of contamination with confirmation soil samples. Remediate to Table 910-1 standards and provide documentation in another Supplemental F-19 if cleaned up immediately and/or F-27 if extended remediation such as landfarming contaminated soil is required. Landfarming must also be approved by surface owner. Documentation must include a figure showing spill area with sample locations plus laboratory results. Date: 12/20/2018

Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401846636	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4651322
690300386	Insp photos 11-13-18	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4651321

Inspection Photos
Location Name: XTO Location 316351
11-13-18



Spill area lookin north



Soil stockpile looking north