

# Final Reclamation Inspection

December 14, 2018

Operator: CHESAPEAKE OPERATING LLC- 16660

API: 05-123-34627

Inspection Document #: 682404271

Weld County, CO

NWNW Section 18 T8N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: HEIBY 18-8-66 #1H  
API: 05-123-34627



**Photo 1.** Photo taken from a portion of the eastern access road, facing West. Operator has performed final reclamation activities throughout the entire access road and well location.



**Photo 2.** Photo taken from a portion of the central access road, facing West. See comments under Photo 1.



Inspection Photos  
Location Name: HEIBY 18-8-66 #1H  
API: 05-123-34627



**Photo 3.** Photo taken from a portion of the access road that crossed an intermittent stream, facing Northwest. See comments under Photo 1.



**Photo 4.** Photo taken from northeast well pad, facing South. See comments under Photo 1. Operator installed straw wattle BMPs but did not properly install BMP (i.e., wattles should have been trenched to properly function).



Inspection Photos  
Location Name: HEIBY 18-8-66 #1H  
API: 05-123-34627



**Photo 5.** Photo taken from northeast well pad, facing West. See comments under Photo 4.



**Photo 6.** Photo taken from central well pad, facing South. See comments under Photo 1.