

Inspection Photos

Operator: BP Production

API: 05-067-07981

Date: 11/29/2018



Photo 1. View of the project area from the northeastern corner facing center. Interim reclamation is not conducted.



Photo 2. View of the southern project area from the southeastern corner facing westward. Revegetation is sparse and appears grazed.



Photo 3. View of the northern project area from the northeastern corner facing westward. Tubing and other debris present within the northeastern project area.



Photo 4. View of more tubing and what appears to be surface owner equipment and debris within the northern project area.