

Inspection Photos

Operator: Rim Operating

API: 05-067-09286

Date: 11/30/2018



Photo 1. View of erosional channel within the southwestern project area, not stabilized. Erosion not addressed.



Photo 2. View of erosion occurring along the access road. Stormwater controls are needed.



Photo 3. Another view of erosion occurring along the access road where rock and sediment transport and deposition is occurring.



Photo 4. View of erosion occurring near the beginning of the access road. Stormwater controls are needed to stabilize erosional downcutting, and sediment transport.