

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/14/2018

Submitted Date:

12/14/2018

Document Number:

680404093

FIELD INSPECTION FORM

Loc ID 322495 Inspector Name: BROWNING, CHUCK On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 53255
Name of Operator: MARALEX RESOURCES INC
Address: P O BOX 338
City: IGNACIO State: CO Zip: 81137

Findings:

- 8 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Graves, Jim	970-858-8550	mrinc20@qwestoffice.net	Operations Manager
Reid, Jordan	(970) 563-4000	maralextechjr@gmail.com	All Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210630	WELL	SI	05/01/2012	GW	045-06386	CALF CANYON-FEDERAL 26-1	TA

General Comment:

Location

Lease Road:			
Type	Access		
comment:			
Corrective ActionL			Date:
Type	Main		
comment:			
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Pipe fence		
Corrective Action:			Date:

Equipment:			corrective date
Type: Gas Meter Run	# 0		
Comment:	Equipment removed.		
Corrective Action:			Date:
Type: Flow Line	#		
Comment:	Multiple 1" & 2" unused risers. Locked out/tagged out.		
Corrective Action:			Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			

Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 210630 Type: WELL API Number: 045-06386 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Last MIT 12/31/2014.
Well TA longer than 6 months with no Form 4 submitted

Corrective Action: Submit Form 4 as directed by Rule 319.b

Date: 01/25/2019

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Blowdown Lined: _____ Pit ID: _____ Lat: 39.515717 Long: -108.740701

Reference Point: SE Other: _____ Length: 20 Width: 20

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action

Date: _____

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment: Fencing removed

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment:

Corrective Action

Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401875856	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4677093
680404094	Inspection photos 12/14/2018	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4677084