

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC  
Location ID: 460195



Flowline with section cut out where leak was found




Flowline pictured in excavation

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC  
Location ID: 460195



**Fluid traveled down hillside ~400 feet, Track hoe at release point**



**Ditch fluid traveled down ~800 feet**

**Inspection Photos**  
**Operator Name: TEP ROCKY MOUNTAIN LLC**  
**Location ID: 460195**



**Ditch fluid traveled down ~800 feet**



**Path fluid took in field, ~250 feet**  
**Stake represents end point of fluid movement**

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC  
Location ID: 460195



**End point with Track hoe on hillside at start point**



**Stake represents end point of fluid**