

Inspection Photos

12/24/2018

Operator: FOUNDATION ENERGY
MANAGEMENT LLC - 10112

Location ID: 447523

Inspection Doc. Number: 682504335
Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos

Operator: FOUNDATION ENERGY MANAGEMENT LLC - 10112

Location ID: 447523



Photo 1: Photo taken from the south end of location, facing southwest. Previous inspections required operator to conduct final reclamation. Photo shows that oil and gas facilities/equipment/trash debris remains on location. Photo also shows access road remains. Unable to find evidence that final reclamation has been conducted in accordance with 1004 rules and requirements.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Doc. Number: 682504335

Inspection Photos
Operator: FOUNDATION ENERGY MANAGEMENT LLC - 10112
Location ID: 447523



Photo 2: Photo taken from the south end of location, facing northwest. See comments under photo 1.

Inspection Photos
Operator: FOUNDATION ENERGY MANAGEMENT LLC - 10112
Location ID: 447523



Photo 3: Photo taken from the south end of location, facing west. See comments under photo 1.



Photo 4: Continued from photo 3. Photo shows abandoned risers remains on the location



Photo 5: Photo taken from the southeast end of the locating, facing east. Photo shows abandoned riser and cable remaining on the location



Photo 6: Photo taken from the southeast end of location, facing north. Previous inspections required operator to conduct final reclamation. Photo shows that oil and gas facilities/equipment/trash debris remains on location. Unable to find evidence that final reclamation has been conducted in accordance with 1004 rules and requirements.



Photo 7: Continued from photo 6. Photo shows contaminated soil due to chemical discharge from the tanks have not been cleaned or removed.



Photo 8: Photo taken from the west end of the location, facing north. Previous inspections required operator to conduct final reclamation. Photo shows that oil and gas facilities/equipment/trash debris remains on location. Unable to find evidence that final reclamation has been conducted in accordance with 1004 rules and requirements.



Photo 9: Photo taken from the north end of the location, facing north. See comments under photo 8.



Photo 10: Photo taken from the north end of the location, facing north. See comments under photo 8.



Photo 11: Photo taken from the west end of the location, facing north. See comments under photo 8.